

TVM-N with FH 50k – Assembly Instruction

1. Unpack the test stand
2. Plug the power supply




3. Check your attachments for these parts



TVM-N with FH 50k – Assembly Instruction

4. Screw the mushroom-shaped part I in the load cell



5. Lay parts II and III underneath the screw IV and fix the load cell with screw IV

